

Field & Technical Services

200 Third Avenue + Carnegie, PA 15106 + Phone: 412-429-2694 + Fax: 412-279-4512

December 1, 2022

Mr. John Sager Wisconsin Department of Natural Resources 1701 N 4th Street Superior, WI 54880

Re: Summary of 2022 Sign Inspection Activities

Koppers Inc. Facility Superior, Wisconsin

Dear Mr. Sager:

On behalf of Beazer East, Inc. (Beazer), Field & Technical Services, LLC (FTS) is pleased to submit this letter summarizing the results of the April 2022 inspection of warning signs posted along the tributary to Crawford Creek (formerly referred to as Outfall 001 drainage ditch) and select areas within the Crawford Creek floodplain located near the Koppers Inc. (KI) facility in Superior, Wisconsin.

In the fall of 2001, at the request of the Wisconsin Department of Natural Resources (WDNR), Beazer posted warning signs along the tributary to Crawford Creek and a portion of the Crawford Creek floodplain located near the KI facility in Superior, Wisconsin. In September 2005, 68 new signs reflecting updated contact information for the WDNR and Douglas County Department of Health and Human Services were posted, and all of the old signs were removed. In general, signs are posted at approximately 250-feet intervals along both sides of the tributary to Crawford Creek from the KI property boundary downstream to the confluence with the Crawford Creek floodplain, and along both sides of the Crawford Creek floodplain from Hammond Avenue downstream to the railroad crossing. Additional signs are posted at potential access areas, such as near roads, hunting stands, bridges, and railroad tracks.

Since the warning signs were initially posted in 2001, periodic inspections have been made to identify damaged, disoriented, and/or missing signs. The most recent sign inspection was conducted on April 26, 2022. During the inspection, a total of 7 warning signs were replaced. All remaining signs were observed to be in good condition.

The construction fencing installed around the tributary to Crawford Creek from Hammond Avenue to the railroad crossing in September 2005 was inspected on April 26, 2022. During the April 26, 2022 inspection, the construction fencing was re-secured to existing posts where necessary during the inspection.

Please feel free to contact Jane Patarcity of Beazer at (412) 208-8813 or the undersigned at (412) 428-9397 if you have any questions or comments regarding the sign inspection activities summarized above.

Sincerely,

Field & Technical Services, LLC

Hank Pappert Project Manager

cc: Jane Patarcity-Beazer

David Bessingpas-ARCADIS



Attachment



Koppers, Inc. Facility Superior, Wisconsin

Snow Fence Inspection

| | Repair/Modification | |
|----------------------|---------------------|------------------------------|
| Fence Segment | Required? | Comments |
| DD1-DD2 | No | Be-attached Force to T-Post |
| DD2-DD3 | No | Be-ortained Force to T-Post |
| DD3-DD4 | Na | The Stacked Force to 1-Post |
| DD4-DD5 | No | The attached Force to T-Posi |
| DD5-DD6 | No | Be atomid Force to T-Post |
| DD6-DD7 | No | Re Hoched Force to T-Past |
| DD7-DD22 | No | Pre- Hached Fonce to T-Post |
| DD22-DD23 | No | Be- Stacked Fence to T-Post |
| DD23-DD24 | No | Re Itahas, Force to T-Post |
| DD24-DD25 | No | Be- Drahyd Fore to T-Past |
| DD25-DD26 | No | Re-attached Force to J-Post |
| DD26-DD27 | Na | Rg- attached Force to I-Post |
| DD27-DD28 | No | Pre- Stadied Force to T-Past |
| DD28-DD1 | No | Be- Hacked Force to I-Fost |

Table 1

Koppers, Inc. Facility Superior, Wisconsin

Summary Warning Sign Inspection

| | Repair/Modification | | |
|--------------|--|--|--|
| | | Comments | |
| | | | |
| | The state of the s | | |
| | | Sign Replaced | |
| - | | Sign Replaced Sign Replaced | |
| | No | J., 1 | |
| | No | | |
| Tree | No | | |
| Tree | No | | |
| Tree | 1 | | |
| Tree | | | |
| Steel T-Post | | | |
| Steel T-Post | | | |
| Steel T-Post | No | Sin Replaced on F-Box | |
| Steel T-Post | No | Sign replices on 1 1051 | |
| Steel T-Post | No | Sign Replaced on F-Post Sign Replaced on T-Post | |
| Tree | No | Jigh Maplaces on 1-10st | |
| Tree | No | | |
| Tree | | | |
| Tree | . 1 | | |
| Tree | 4 / | | |
| Tree | N _a | | |
| Tree | No | | |
| Tree | | Sign Replaced | |
| Tree | No | | |
| Tree | No | | |
| Tree | | | |
| Tree | | | |
| Tree | . 1 | | |
| | | | |
| | | | |
| | | S. B.d. 1. TO.1 | |
| | 16 | Sign Replaced on T-Post | |
| | Ma | sigh incplaced on 1-165t | |
| | A / | | |
| | | | |
| | | | |
| | NI. | | |
| | 16 | | |
| | 100 | | |
| | | | |
| | Tree Tree Steel T-Post Steel T-Post Steel T-Post Steel T-Post Steel T-Post Tree Tree Tree Tree Tree Tree Tree Tre | Secured To Required? Steel T-Post No Tree No Steel T-Post No Tree No Steel T-Post No Steel T-Post No Steel T-Post No Steel T-Post No | |

Table 1

Koppers, Inc. Facility Superior, Wisconsin

Summary Warning Sign Inspection

| Sign ID | Secured To | Repair/Modification Required? | Comments |
|---------|--------------|----------------------------------|--|
| DD-7 | Tree | No | |
| DD-8 | Tree | No | |
| DD-9 | Tree | No | |
| DD-10 | Tree | No | |
| DD-11 | Tree | No | |
| DD-12 | Tree | 1/2 | |
| DD-13 | Tree | 100 | |
| DD-14 | Tree | Na | |
| DD-15 | Tree | No | |
| DD-16 | Tree | 1/2 | |
| DD-17 | Tree | Na | |
| DD-18 | Tree | No | |
| DD-19 | Tree | No | |
| DD-20 | Tree | No | |
| DD-21 | Tree | No | |
| DD-22 | Tree | No | |
| DD-23 | Tree | Ma | |
| DD-24 | Tree | No | |
| DD-25 | Tree | No | |
| DD-26 | Tree | No | |
| DD-27 | Steel T-Post | NA | |
| DD-28 | Tree | No | |
| DD-29 | Tree | No | |
| DD-30 | Tree | No | |
| DD-31 | Tree | No | Sign on T-Post Sign on T-Post Sign on T-Post |
| DD-32 | Tree | No | |
| DD-33 | Tree | No | Sign-on T-Post |
| DD-34 | Tree | No | Sian on T-Post |