From:	Jeff Anderson
То:	Paddock, Jeffrey J - DNR
Subject:	Chippewa Quick Mart Suggested Soil Boring Locations
Date:	Wednesday, March 13, 2024 4:40:21 PM
Attachments:	image001.png
	image002.png
	image003.png
	2971 001.pdf

CAUTION: This email originated from outside the organization. Do not click links or open attachments unless you recognize the sender and know the content is safe.


Hi Jeff,

Attached is a map where I thought we could put additional soil borings to further assess the TCE detections in gw at previous borings GP-1 and GP-2. I think locations would give us enough data to presumably either define the contamination determine an off-site source is apparent. Anyways food for thought before we discuss on Friday. Thanks. Jeff



MSA. Jeff Anderson, PE | Team Leader MSA Professional Services, Inc. +1 (218) 499-3175 in ♥ f

From: (0Z1HP9EBETWC6-0DVQ28DQTXSPB) <jkanderson@msa-ps.com> Sent: Wednesday, March 13, 2024 4:35 PM **To:** Jeff Anderson < jkanderson@msa-ps.com> Subject: Attached Image



ATTACHMENT B.2.b

RESIDUAL SOIL CONTAMINATION

FORMER CHIPPEWA QUICK MART 122 EAST BROADWAY GLIDDEN, ASHLAND COUNTY, WISCONSIN



All data shown in this exhibit is approximate for display purposes only and does not reflect actual survey data.

Data Sources Ashland County, Esri Community Maps Contributors, © OpenStreetMap, Microsoft, Esri, HERE Garmin, SafeGraph, GeoTechnologies, Inc. METI/NASA, USGS, EPA, NPS, US Census Bureau, USDA



20 Feet



From:	Jeff Anderson
То:	Paddock, Jeffrey J - DNR
Subject:	Chippewa Quick Mart - Glidden, WI (BRRTs #03-02-580266)
Date:	Wednesday, March 13, 2024 12:55:07 PM
Attachments:	image001.png
	image002.png
	image003.png
	B.3.b Groundwater Isoconcentration.pdf
	A.1 Groundwater Analytical Results.pdf

CAUTION: This email originated from outside the organization. Do not click links or open attachments unless you recognize the sender and know the content is safe.

Hi Jeff,

Wondering if you might have some time for a quick discussion about the Chippewa Quick Mart site in Glidden, WI. Erica Klingfus, who was managing the project at MSA took a job with the MPCA and I inherited the project. I did a quick review and have attached the Groundwater Sampling Map and the GW Analytical Results Table. It appears that a couple lower concentration TCE detections (PAL exceedances) are at issue here. It also seems that a few well positioned borings and gw sampling on the north and east sides of the property would: a) either give us on-site definition; or (b) point towards an off-site determination. Maybe we need to put one in the alley ROW, also. The owner is pretty resistant to any additional work as he thinks it is coming from an off-site source, but I feel I can convince him to do a few borings to provide better overall information about the TCE detections (gw).

If you have some time, I'd just like to discuss what would be an agreeable amount of borings and there locations. Thanks for any input you may have and consideration of a quick phone call. I could also e-mail you a map of what I am thinking for discussion. Thanks. Jeff



Jeff Anderson, PE | Team Leader MSA Professional Services, Inc. +1 (218) 499-3175