

Long Lake North Landing


Stormwater Mitigation



*Runoff flows down entire landing driveway to the lake (5/23/16)
(4,500 ft² of hard surface – need 937.5 ft³ of rock infiltration area to capture a 1” rain.)*



Install rock infiltration area under parking areas. Keep shallow to maintain separation to water table. East side installed in 2016. Top portion has sedimented in. Remove dirty rock and replace with clean.



*Rock infiltration – west side
Rock size for both 1 1/2” clean, **level bottom**, rock across entire surface currently dirt.*