# Mine Cross Section Schematic

Massive Ore (Primarily Zinc) | Stringer Ore (Primarily Copper) | Crown Pillar | Bedrock | Glacial Overburden | Initial Mining Areas Years 1-4

SCALE: NOT TO SCALE




## TOP VIEW (500 LEVEL)




## SIDE VIEW




## END VIEW