

Taylor County #13 Photos

Taylor County proposes to rehab 2.5 miles of ATV/UTV trail in the **Camp 8** Trail System (**Maple Loop**). This trail segment has never received rehab funds, and is a loam soil type that has degraded over the years. The county would like to reshape and level the trail to better shed water, repairing and preventing future washouts and potholes. The county proposes to add fabric and breaker type material to two 80' segments, install 3 12"x16' culverts, and add a 4-6" cap of 2" crushed gravel. Taylor County has applied for RTA funds for a 50% cost share.

#1 Blocked Culvert Water Running Down Trail_1_3



#2 Wet Hole Needs Fill and Reshaping_10



#3 Rutted Hill Needs Fill and Dozer Work_9



#4 Rutted Hill Needs Fill And Dozer Work_8_3



#5 Needs Fill and Dozer Work_7



#6 Needs Fill and Dozer Work _6



#7 Needs Culvert, Fill and Dozer Work_11_3



#8 Decommission This Area and Rehab_12_3



#9 Culvert and Fill, Dozer Work_13_3



#10 Rutted Hill, Fill and Dozer Work _2_3



#11 Decommission and Reroute Trail_3_3



#12 Example of Narrow Trail_4_3



#13 Dozer Work and Fill Raise Trail_5_3.JPG

