

**Table E1S-1  
GW Partners  
Lower Fox River - OU-1  
04G007**

**High Subgrade Poling and Core Sample Collection Results  
DMU-1 E1**

Collection Date	ID	Actual Location		Soft Sediment Coring Thickness (Feet)	Poling Depth (Light Effort) (Feet)	Poling Depth (To Refusal) (Feet)	Comments
		Northing	Easting				
<b>Poling</b>							
11/8/2006	DMU-1E1-P1	142378.67	2371797.08	0.58	1.00	2.40	
11/8/2006	DMU-1E1-P2	142329.28	2371755.14	0.48	0.60	1.20	
11/8/2006	DMU-1E1-P3	142365.07	2371676.54	0.77	1.50	3.10	
11/8/2006	DMU-1E1-P4	142336.75	2371616.38	0.40	0.60	1.10	
11/8/2006	DMU-1E1-P5	142288.99	2371612.65	-	0.30	1.90	
11/8/2006	DMU-1E1-P6	142262.43	2371621.97	NR	1.10	2.10	
11/8/2006	DMU-1E1-P7	142239.05	2371707.29	0.43	0.90	1.60	
11/8/2006	DMU-1E1-P8	142219.24	2371707.29	0.33	0.60	1.40	
11/8/2006	DMU-1E1-P9	142205.73	2371722.44	0.30	0.70	1.50	
11/8/2006	DMU-1E1-P10	142275.63	2371733.85	0.36	0.90	1.90	
11/8/2006	DMU-1E1-P11	142260.49	2371763.21	0.46	1.20	1.50	
11/8/2006	DMU-1E1-P12	142281.7	2371858.06	0.68	1.40	3.90	
<b>Coring</b>							
11/8/2006	DMU-1E1-HS1	142337.6	2371769.92	0.30	1.40	1.90	
11/8/2006	DMU-1E1-HS2	142233.47	2371614.46	NR	0.90	1.90	
11/8/2006	DMU-1E1-HS3	142236.99	2371769.51	0.30	0.80	1.10	
11/8/2006	DMU-1E1-HS4	142249.34	2371804.23	0.09	1.30	2.20	

Notes:

- = No Core Taken or No Poling Performed  
NR = No Recovery

Prepared by: TRV  
Checked by: SVF