

From: Kleinberg, Andrew <Kleinberg.Andrew@epa.gov>
Sent: Tuesday, November 14, 2023 3:09 PM
To: Denice Nelson
Cc: Heather.Ziegelbauer@jacobs.com; Krueger, Sarah E - DNR; Carey, Angela J - DNR
Subject: TYCO - No Anchoring Signs Comments
Attachments: IMG_1489.jpg

**CAUTION: This email originated from outside the organization.
Do not click links or open attachments unless you recognize the sender and know the content is safe.**

Hey Denice,

Please see the following comments related to the new no anchoring signage (a photo of the current boom landing sign is included for reference):

1. Include a statement "Arsenic impacted sediments" on all of the signs. This could be similar to the original signs which used a header/footer "title" on each sign.
2. The no anchoring symbol should fit completely within the specified area and none of the arrows/text should obstruct the area that is restricted. The colors should match so people can connect the symbol to the area and text visually.
3. If practicable, all the signs should show the same extent.
4. For consistency, the last two signs should use the same symbology for the "you are here" sign.
5. All the signs should highlight the no anchoring area the same way, red is recommended to reflect the related text.

Thank you,

Andrew Kleinberg

Project Manager - Geologist
RCRA Corrective Action Section 2
Land, Chemicals & Redevelopment Division, Region 5, U.S. EPA
77 West Jackson Blvd. (LR-16J), Chicago, IL 60604
(312) 353-4374
Kleinberg.Andrew@epa.gov



ADVISORY: Check against these backwash transmitters on all boats and trailers in the boat launch area. The backwash transmitters are located in the dock or backwash area. If you have a backwash transmitter, please check it against the backwash transmitters on the dock or backwash area. If you do not have a backwash transmitter, please check it against the backwash transmitters on the dock or backwash area. If you do not have a backwash transmitter, please check it against the backwash transmitters on the dock or backwash area. If you do not have a backwash transmitter, please check it against the backwash transmitters on the dock or backwash area.

SPORT FISHING RESTORATION

DAILY BOAT LAUNCH FEE
\$5.00

16th Ave. PEOPLE enjoy clean, healthy rivers and for many types of outdoor recreation.

Menominee

Marinette

FISH PASSAGE AT DAMS
 The Menominee River is an important spawning location for lake sturgeon, but dams impede the movement of these primitive fish to their preferred spawning grounds. The owners of the Menominee and Park Mill dams are working to safely pass sturgeon around the dams, allowing them to reach spawning grounds farther upstream. Young sturgeon will be able to spend more time in the relative safety of the river, giving them a better chance of survival once they return to Lake Michigan to grow into adults.

SEDIMENT CLEANUP
 A great step towards restoring the river has come from cleaning up contaminated sediments. Sediment impacted areas existed along the river corridor. Contaminants included coal tar, arsenic, and heavy metals. A shoreline site characterization waste audit was completed in the 1990s. Remediation work was completed in 2005, resulting in improved river conditions for fish.

NO ANCHORING WITHIN DESIGNATED AREA

YOU ARE HERE

Arsenic impacted sediments, for more information call: 608-264-6123
 Marinette City Ordinance 2175

WISCONSIN COASTAL MANAGEMENT PROGRAM

Blanchet's