

From: Denice Nelson <denice.karen.nelson@jci.com>
Sent: Wednesday, January 3, 2024 2:32 PM
To: Kleinberg, Andrew
Cc: Heather.Ziegelbauer@jacobs.com; Krueger, Sarah E - DNR; Carey, Angela J - DNR; Ryan Suennen
Subject: RE: TYCO - No Anchoring Signs Comments
Attachments: Stanton Sign Updates_January 2024.pdf

**CAUTION: This email originated from outside the organization.
Do not click links or open attachments unless you recognize the sender and know the content is safe.**

Hi Andrew – attached are the revised signs incorporating your comments.

Please let me know if these are approved and we will get them posted.

Thanks
Denice

Denice Nelson
Senior Director, Remediation and Strategy
[Johnson Controls](#)

+1 651 280 7259 cell

The power behind your mission

This email (including any attachments) may contain information that is private or business confidential. If you received this email in error, please delete it from your system without copying it and notify sender by reply email so that our records can be corrected.

From: Kleinberg, Andrew <Kleinberg.Andrew@epa.gov>
Sent: Tuesday, November 14, 2023 3:09 PM
To: Denice Nelson <denice.karen.nelson@jci.com>
Cc: Heather.Ziegelbauer@jacobs.com; Krueger, Sarah E - DNR <sarah.krueger@wisconsin.gov>; angela.carey@wisconsin.gov
Subject: TYCO - No Anchoring Signs Comments

Hey Denice,

Please see the following comments related to the new no anchoring signage (a photo of the current boom landing sign is included for reference):

1. Include a statement “Arsenic impacted sediments” on all of the signs. This could be similar to the original signs which used a header/footer “title” on each sign.

2. The no anchoring symbol should fit completely within the specified area and none of the arrows/text should obstruct the area that is restricted. The colors should match so people can connect the symbol to the area and text visually.
3. If practicable, all the signs should show the same extent.
4. For consistency, the last two signs should use the same symbology for the “you are here” sign.
5. All the signs should highlight the no anchoring area the same way, red is recommended to reflect the related text.

Thank you,

Andrew Kleinberg

Project Manager - Geologist

RCRA Corrective Action Section 2

Land, Chemicals & Redevelopment Division, Region 5, U.S. EPA

77 West Jackson Blvd. (LR-16J), Chicago, IL 60604

(312) 353-4374

Kleinberg.Andrew@epa.gov

NO ANCHORING WITHIN DESIGNATED AREA

Stephenson Island
Boat Landing

River Park
Boat Launch

Menominee River

Boom Landing
Boat Landing

Railroad Dock
Boat Access Site

YOU ARE
HERE

SHORELINE

Sixth Street Slip
Boat Landing

Arsenic impacted sediments. Scan QR code for more information or call 715-735-7411.



NO ANCHORING WITHIN DESIGNATED AREA

Stephenson Island
Boat Landing

River Park
Boat Launch

Menominee River

Railroad Dock
Boat Access Site

YOU ARE
HERE

Boom Landing
Boat Landing

SHORELINE

Sixth Street Slip
Boat Landing



Arsenic impacted sediments. Scan QR code for more information or call 715-735-7411.

**NO ANCHORING
WITHIN
DESIGNATED
AREA**

Stephenson Island
Boat Landing

River Park
Boat Launch

Menominee River

Boom Landing
Boat Landing

Railroad Dock
Boat Access Site

**YOU ARE
HERE**

SHORELINE

Sixth Street Slip
Boat Landing

Arsenic impacted sediments. Scan QR code for more information or call 715-735-7411.



**NO ANCHORING
WITHIN
DESIGNATED
AREA**

Stephenson Island
Boat Landing

River Park
Boat Launch

Menominee River

Boom Landing
Boat Landing

SHORELINE



Sixth Street Slip
Boat Landing

Railroad Dock
Boat Access Site

**YOU ARE
HERE**



Arsenic impacted sediments. Scan QR code for more information or call 715-735-7411.



NO ANCHORING WITHIN DESIGNATED AREA



**YOU ARE
HERE**

River Park
Boat Launch

Stephenson Island
Boat Landing

Boom Landing
Boat Landing

SHORELINE

Sixth Street Slip
Boat Landing

Railroad Dock
Boat Access Site

Arsenic impacted sediments. Scan QR code for more information or call 715-735-7411.



NO ANCHORING WITHIN DESIGNATED AREA



SHORELINE

YOU ARE
HERE

Arsenic impacted sediments. Scan QR code for more information or call 715-735-7411.

