
De Pere Dam
Little Kaukauna Dam
RSW 03 May 2005 n:\foxsh\gis\maps\doc_ou3kriging\remediationfprints_ou3_p506070_v1.mxd
LOWER FOX RIVER
OPERABLE UNIT 3
Figure 2-18
Estimated Remediation Footprints
Remediation footprints based on estimated depths of contamination.
Level of significance
0.5
0.4
0.3
0
1,000
2,000
ft
0
500
m
Limno-Tech, Inc.
Ann Arbor, Michigan