## WI DNR Public Record Provision of the Energy Policy Act of 2005

## **Summary Information For Releases**

Number of Confirmed UST Relea	ses: <u>47</u>	
Release reporting Period Dates	10/1/17	To: 9/30/18

## **Summary Information For Release Sources And Causes**

	Cause															
Source		Spill Overfill		erfill	Phys/Mech Damage		Corrosion		Install Problem		Other		Unknown			
	#	%	#	%	#	%	#	%	#	%	#	%	#	%	#	%
Tank	33	100	1	3	1	3	0	0	10	30	0	0	1	3	20	61
Piping	2	100	0	0	0	0	1	50	0	0	0	0	0	0	1	50
Dispenser	8	100	1	12.5	1	12.5	1	12.5	1	12.5	0	0	0	0	4	50
STP	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Delivery Problem	1	100	0	0	1	100	0	0	0	0	0	0	0	0	0	0
Other	3	100	1	33	0	0	0	0	0	0	0	0	0	0	2	67
Totals	47	100	3	6.4	3	6.4	2	4.3	11	23.4	0	0	1	2.1	27	57.4

<sup># =</sup> number, % = percent of total number

Note: Release, source and cause information is based on [state: describe universe of tanks]. Source and cause data were collected using [state: describe data-gathering technique(s)].

[State: Provide information here on how the public can obtain site-specific UST information on compliance and releases.]