

Thompson, Matthew A - DNR

From: Mark Meurette <mmeurette@mmm.com>
Sent: Monday, April 18, 2016 8:27 AM
To: Thompson, Matthew A - DNR
Subject: Annual Cap Inspection - 3M Wausau
Attachments: East Parking Lot 3-18-16.JPG; East Parking Lot Inspection 3-18-16.pdf; East Parking Lot Part 2 3-18-16.JPG; South Parking Lot 3-18-16.JPG; South Parking Lot Inspection 3-18-16.pdf

Hi Matt,

I received your voicemail. Attached is the annual cap inspection (the caps look great) for the 3M Wausau facility and below is my contact information. Let me know if you have any questions and thank you for your help,

Mark



Mark Meurette | EHS Engineer
3M Industrial Mineral Division
3M Wausau, WI, 144 Rosecrans Street | Wausau, WI 54401
Office: 715 845 0282
mmeurette@mmm.com | www.3M.com

SOUTH
↑

Attachment 1. Barrier Inspection and Maintenance Log, 3M Parking Lot, Wausau, Wisconsin.

Date	Inspector	Condition of Cap (Excellent, Good, Fair, Poor)	Recommendations	Required Repairs	Has recommended maintenance from the previous inspection been implemented?
3-18-16	MARK MEURETTE	GOOD	NONE	NONE	NA





NOTICE TO ALL PERSONNEL
NO PERSONNEL ALLOWED IN THIS AREA
EXCEPT BY AUTHORITY OF THE
SUPERVISOR. ALL PERSONNEL MUST
WEAR SAFETY SHOES AND SAFETY
GLASSES AT ALL TIMES. NO ALCOHOL
OR DRUGS TO BE USED IN THIS AREA.

DANGER
OVERHEAD LIFT
DO NOT ENTER

1F

EAST
↑

Attachment 1. Barrier Inspection and Maintenance Log, 3M Parking Lot, Wausau, Wisconsin.

Date	Inspector	Condition of Cap (Excellent, Good, Fair, Poor)	Recommendations	Required Repairs	Has recommended maintenance from the previous inspection been implemented?
3-18-16	MARK MEURETTE	GOOD	NONE	NONE	NA

