

1-4-24

Remediation and Redevelopment West Central Region
Wisconsin Department of Natural Resources
1300 W Clairemont Ave
Eau Claire, WI 54701-6127

Dear Mr. Matt Thompson,

3M has enclosed with this letter the annual Barrier/Cap Inspection Log for the two areas located at the 144 Rosecrans location that are subject to continuing obligations specified in Barrier/Cap Maintenance Plans. The two areas are the East Parking Lot and South Parking Lot which are defined in the Remediation and Redevelopment Tracking System (BRRTS) as #02-37-000273 and #03-37-298-678 respectively.

The two Barrier/Cap Inspection Logs show that there were no signs of significant fissures, cracks or other potential problems in both asphalt caps and therefore no repairs to the capped areas are necessary. The photos taken on the day of the inspection are available upon request.

Please contact me if you have any questions about this letter or the enclosures. This letter is being submitted via email and will not be mailed to you unless specifically requested.

Sincerely,



Mark Meurette
EHS Engineer
715-845-0282

Enclosures:

2024 Annual Barrier/Cap Inspection Log for East Parking Lot (BRRTS #02-37-000273)

2024 Annual Barrier/Cap Inspection Log for South Parking Lot (BRRTS #03-37-298678)

SOUTH
^

Attachment 1. Barrier Inspection and Maintenance Log, 3M Parking Lot, Wausau, Wisconsin.

Date	Inspector	Condition of Cap (Excellent, Good, Fair, Poor)	Recommendations	Required Repairs	Has recommended maintenance from the previous inspection been implemented?
1-4-24	M. MEURETTE	GOOD	NONE	NONE	NA

EAST
^

Attachment 1. Barrier Inspection and Maintenance Log, 3M Parking Lot, Wausau, Wisconsin.

Date	Inspector	Condition of Cap (Excellent, Good, Fair, Poor)	Recommendations	Required Repairs	Has recommended maintenance from the previous inspection been implemented?
1-4-24	M. MEURETTE	GOOD	NONE	NONE	NA