

Gutknecht, Lisa A - DNR

From: Justin Pettinelli <jjpettinelli@mmm.com>
Sent: Friday, April 24, 2015 1:00 PM
To: Gutknecht, Lisa A - DNR
Cc: Mark Meurette; Trask (Cota), Jennine; Robbennolt, Rebecca
Subject: 3M Wausau Parking Lot Annual Inspection 2015 BRRTS# 0237000273
Attachments: South Parking Lot Barrier Inspection 4-24-15.pdf

Hello Lisa:

Here is a copy of the 2015 parking lit inspection. Let me know if you have any questions, thanks!



Justin J. Pettinelli, P.E. | Senior Environmental Engineer
3M EHSO - Corporate Environmental Programs
3M Center | Bldg 224-5W-17 | St. Paul, MN | 55144-1000
Office: 651 737 3481 | Triminet: 737 3481 | Cube: 5A22
jjpettinelli@mmm.com | 3M.com | [3M Connections Profile](#) (3M Internal Only)

Attachment 1. Barrier Inspection and Maintenance Log, 3M Parking Lot, Wausau, Wisconsin.

Date	Inspector	Condition of Cap (Excellent, Good, Fair, Poor)	Recommendations	Required Repairs	Has recommended maintenance from the previous inspection been implemented?
4-24-15	MARK MEURETTE	GOOD	NONE	NONE	NA

