

From: SDP <sampson.parsons@gmail.com>
Sent: Monday, January 30, 2023 4:49 PM
To: McKnight, Kevin - DNR
Subject: Amcast, Cedarburg, contaminant migration
Attachments: Amcast North 1.jpg

Follow Up Flag: Follow up
Flag Status: Flagged

**CAUTION: This email originated from outside the organization.
Do not click links or open attachments unless you recognize the sender and know the content is safe.**

Hi Mr. McKnight,

As a supplement to the [video](#) of the water runoff problem at the Amcast North site, here is a photo of the broken downspout that was temporarily repaired by the next door neighbor, after the property owner ignored the problem for years. The downspout is attached to the same remaining Amcast building as seen in the video.

The next door neighbor's backyard has known near-surface contamination from the Amcast North site. It arrived there and beyond via rainwater and snowmelt runoff. I think it is likely that the continued flooding due to maintenance neglect is causing further migration due to this unmanaged rainwater and snowmelt.

I think it is likely that the Amast property owner has failed to "Mitigate and halt the migration of PCB contamination beyond the boundaries of the Properties, per Wis. Stat. §292.11 (3)" despite his insufficient monthly copy-and-paste reports that claim he has been "performing such tasks as re-routing downspouts away from areas of concern" for the past 4+ years.

Thank you. (I am a concerned resident, not a local official in any capacity.)
Sampson Daniel Parsons
Cedarburg, WI
414-640-3474

Amcast North 1.jpg

