

## WORK PLAN COMMENTS

The correct BRRTS number: 02-13-583366

Change one boring location at each burn pit (See attached)

Add one boring location at each burn pit (See attached)

Proposed sample depths at West Burn Pit acceptable (No known soil disturbances)

Change proposed sample depth at East Burn Pit to:

1-2 feet below ground surface

At the water table, as proposed

The East Burn Pit may have had past soil handling activities

The abbreviated parameter list is acceptable for this initial investigation

Field procedures and sample collection QA/QC protocols are acceptable

PFAS specific procedures appear acceptable

Will SGS North America be the lab used for these samples?

If these comments/changes are acceptable to Dane County the work can proceed as soon as planned

**Note: if contamination detected in either soil and/or groundwater follow-up investigation and possible remedial action will be required by the Department**




Figure 3. Pearson Street/East Burn Pit Sample Locations.



