Tony Evers, Governor Preston D. Cole, Secretary Telephone 608-266-2621 Toll Free 1-888-936-7463 TTY Access via relay - 711



May 25, 2022

Enbridge Energy, Limited Partnership Karl F. Beaster, P.G. 11 East Superior Street Suite 125 Duluth, MN 55802

Transmitted via electronic mail

Subject:

Review of Supplemental Site Investigation Report Enbridge Line 13 Blackhawk Valve Jefferson County, Wisconsin BRRTS# 02-28-586199

Dear Mr. Beaster:

On March 30, 2022, the Wisconsin Department of Natural Resources (Department) received the Supplemental Site Investigation Report (Report) for Enbridge Line 13 Blackhawk Valve, in Jefferson County, Wisconsin. The Report was submitted with the appropriate fee for Department review and response, per Wis. Admin. Code § NR 749.04(1). The Department has reviewed the Report for compliance with Wis. Admin. Code ch. NR 716 and provides the following comments.

<u>Review</u>

The investigative work completed to date has further characterized the impacts of the release and the hydrogeologic setting of the site. The Department has identified two areas where additional investigation is needed.

- 1. Additional groundwater investigation is needed to evaluate the vertical extent of trichloroethene (TCE) near monitoring well MW-6. The Department recommends you install and sample a deeper piezometer near monitoring well MW-6. Collect soil samples during the associated drilling.
- 2. Additional investigation is needed to evaluate the extent of non-aqueous phase liquid (NAPL) around soil boring IS-36. The Department recommends a shallow monitoring well be installed and sampled to evaluate if there is recoverable NAPL.

Groundwater shall be sampled quarterly. Select private wells (listed below) shall be sampled annually. The sampling schedule and selection of private wells will be periodically re-evaluated by the Department. All sampling results shall be reported to the Department within 10 business days of receiving the results, per Wis. Admin. Code ch. NR 716.14. Water supply well sampling results shall be reported to the well owner and occupant within 10 business days of receiving sampling results, per Wis. Admin. Code ch. NR 716.14.

Well Name	Address
Ness	N1811 Blackhawk Island Road
	Fort Atkinson, WI 53538
Pundsack	W6871 Hartwig Lane
	Fort Atkinson, WI 53538



TT 1 1	
Hachtel	W6876 Hartwig Lane
	Fort Atkinson, WI 53538
Wilson	N1828 Blackhawk Island Road
	Fort Atkinson, WI 53538
Berndt	N1859 Blackhawk Island Road
	Fort Atkinson, WI 53538
Lubbert A	W6856 Christie Ct
	Fort Atkinson, WI 53538
Lubbert B	W6851 Christie Ct
	Fort Atkinson, WI 53538
Lubbert C	W6855 Christie Ct
	Fort Atkinson, WI 53538
Lubbert D	W6856 Christie Ct
	Fort Atkinson, WI 53538
Gehrke	N1804 Blackhawk Island Road
	Fort Atkinson WI 53538
Krause (formerly Maasz)	W6884 Hartwig Lane
	Fort Atkinson WI 53538
Macleod	N1908 Blackhawk Island Road
	Fort Atkinson WI 53538

The Department appreciates the efforts you are taking to address the contamination at this site. If you have any questions about this letter, please contact me at (608) 219-2182 or at caroline.rice@wisconsin.gov.

Sincerely,

Catoline Rie

Caroline Rice Hydrogeologist Remediation and Redevelopment Program Wisconsin Department of Natural Resources

cc: Issac Ross, DNR Timothy Huff, WSP USA Inc.