



B.M. 'X' Spike in regulatory sign post
at public access on east side of lake
Assumed Elevation 100.00'
Water Elevation 94.00'



EQUIPMENT RECORDING SONAR MAPPED

JUNE 1975
MONTH YEAR

TOPOGRAPHIC SYMBOLS		LAKE BOTTOM SYMBOLS	
(B) Brush	() Steep slope	P. Peat	B Boulders
(PW) Partly wooded	(---) Indefinite shoreline	Mh. Muck	⊙ Stumps & Snags
(W) Wooded	(---) Marsh	C. Clay	⊙ Rock danger to navigation
(C) Cleared	(---) Spring	M. Marl	T Submergent vegetation
(P) Pastured	(---) Intermittent stream	Sd. Sand	↓ Emergent vegetation
(A) Agricultural	(---) Permanent inlet	St. Silt	⊙ Floating vegetation
B.M. Bench Mark	(---) Permanent outlet	Gr. Gravel	⊙ Brush shelters
■ Dwelling	(---) Dam	R. Rubble	
⊙ Resort	(---) D.N.R. State owned land	Br. Bedrock	
⊙ Camp			



SPECIES OF FISH	Abundance		
	Abundant	Common	Present
Muskie			X
N. Pike		X	
Walleye			X
L. M. Bass	X		
S. M. Bass			
Panfish	X		
Trout			

WATER AREA 96 ACRES
 UNDER 3 FT. 21 %
 OVER 20 FT. 0 %
 MAX. DEPTH 19 FEET.
 TOTAL ALK. 103 P.P.M.
 VOLUME 517 ACRE FT.
 MAIN SHORELINE 2.43 MI.
 ISLAND SHORELINE .095 MI.

Source: Wisconsin Department of Natural Resources 608-266-2621
Munger Lake – Oconto County, Wisconsin DNR Lake Map
Date - Jun 1975 - Historical Lake Map - Not for Navigation
A Public Document - Please Identify the Source when using it.