

EQUIPMENT RECORDING SONAR MAPPED JUNE 1966  
MO. YR.


WATER ELEV. 98.59

East Troy 1 mi. S.E.

B.M. 'X' Square in culvert at outlet  
at N.E. Corner of Lake  
Assumed Elev. 100.00'  
Water Elev. 98.59'

- TOPOGRAPHIC SYMBOLS
- (P) Brush
  - (PW) Partially wooded
  - (W) Wooded
  - (C) Cleared
  - (P) Pastured
  - (A) Agricultural
  - B.M. Bench Mark
  - Dwelling
  - Resort
  - ||||| Steep slope
  - - - Indefinite shoreline
  - Marsh
  - o Spring
  - Intermittent stream
  - Permanent inlet
  - Permanent outlet
  - Dam

- LAKE BOTTOM SYMBOLS
- P. Peat
  - Mk. Muck
  - C. Clay
  - M. Marl
  - Sd. Sand
  - St. Silt
  - Gr. Gravel
  - R. Rubble
  - Br. Bedrock
  - Stumps & Snags
  - Submergent vegetation
  - Emergent vegetation
  - Floating vegetation



◇ Access      ◆ Access with Parking      ◆ Boat Livery  
Field work by: H. Schwenn      Drawn by: E. Eaton

SPECIES OF FISH		
	Abundant	Rare
Muskie		
N. Pike		X
Walleye		
L.M. Bass	X	
S.M. Bass		
Panfish	X	
Trout		

AREA 27.3 ACRES  
UNDER 3FT. 50 %  
OVER 20FT. 0 %  
VOLUME 90.3 ACRE FT.  
TOTAL ALK. 133 P.P.M.  
SHORELINE .8 MILES  
MAX. DEPTH 7 FEET