



EQUIPMENT RECORDING SONAR MAPPED SEPT. 1975
MONTH YEAR

- | TOPOGRAPHIC SYMBOLS | | LAKE BOTTOM SYMBOLS | |
|-----------------------|-------------------------------|---------------------|-----------------------------|
| (B) Brush | Steep slope | P. Peat | B Boulders |
| (PW) Partially wooded | ----- Indefinite shoreline | Mk. Muck | ⊙ Stumps & Snags |
| (W) Wooded | ----- Marsh | C. Clay | ⊙ Rock danger to navigation |
| (C) Cleared | ----- Spring | M. Marl | T Submergent vegetation |
| (P) Pastured | ----- Intermittent stream | Sd. Sand | ⊥ Emergent vegetation |
| (A) Agricultural | ----- Permanent inlet | St. Silt | ⊥ Floating vegetation |
| B.M. Bench Mark | ----- Permanent outlet | Gr. Gravel | ⊥ Brush shelters |
| ■ Dwelling | ----- Dam | R. Rubble | |
| □ Resort | ----- D.N.R. State owned land | Br. Bedrock | |
| □ Camp | | | |

SPECIES OF FISH	Abundance	
	Common	Present
Muskie	X	X
N. Pike	X	X
Walleye	X	X
L. M. Boss	X	X
S. M. Boss	X	X
Panfish	X	
Trout		

WATER AREA 625.6 ACRES
 UNDER 3 FT. 4.41 %
 OVER 20 FT. 45.5 %
 MAX. DEPTH 32 FEET.
 TOTAL ALK. 37 P.P.M.
 VOLUME 10838.46 ACRE FT.
 MAIN SHORELINE 7.4 MI.
 ISLAND SHORELINE 0 MI.



Access Access with Parking Boat Livery
 Drawn by G. Thuesen
 Field work by J. Smith

B.M. "X" 2066-A is a cast aluminum cap set in concrete post 6' above ground (cap is stamped "Dept. of Natural Resources") at the wayside on West of 1/2 of West access, and 75' North of edge of water. Assumed elevation = 100.00'. Water level = 92.69'

Source: Wisconsin Department of Natural Resources 608-266-2621
Crescent Lake – Oneida County, Wisconsin - DNR Lake Map
Date – Sep 1975 - Historical Lake Map - Not for Navigation
A Public Document - Please Identify the Source when using it.