



B.M. 'X' Top of E. end of N. concrete retaining wall of dam
Assumed elevation 100.00'
Water level 95.35'

COLFAX

EQUIPMENT SONAR & POLE MAPPED MAY 1970
MONTH YEAR

- TOPOGRAPHIC SYMBOLS
- (B) Brush
 - (PW) Partially wooded
 - (W) Wooded
 - (C) Cleared
 - (P) Pastured
 - (A) Agricultural
 - B.M. Bench Mark
 - Dwelling
 - ▣ Resort
 - ▢ Camp
 - ▨ Steep slope
 - Indefinite shoreline
 - ▧ Marsh
 - Spring
 - Intermittent stream
 - Permanent inlet
 - Permanent outlet
 - Dam
 - D.N.R. State owned land

- LAKE BOTTOM SYMBOLS
- P. Peat
 - Mk. Muck
 - C. Clay
 - M. Marl
 - Sd. Sand
 - St. Silt
 - Gr. Gravel
 - R. Rubble
 - Br. Bedrock
 - B Boulders
 - ⊙ Stumps & Snags
 - ⊙ Rock danger to navigation
 - T Submergent vegetation
 - ⊥ Emergent vegetation
 - Floating vegetation
 - ⊕ Brush shelters



◆ Access ◆ Access with Parking ◆ Boat Livery

Drawn by: C. Holt
Field work by: S. Hagen

SPECIES OF FISH	ABUNDANCE		
	Abundant	Common	Present
Muskie			
N. Pike			
Walleye			
L.M. Bass			
S.M. Bass			
Panfish			X
Trout			X

WATER AREA 9.5 ACRES
UNDER 3 FT. 36 %
OVER 20 FT. 0 %
MAX. DEPTH 13 FEET.
TOTAL ALK. 65 P.P.M.
VOLUME 41.7 ACRE FT.
SHORELINE 1.47 MILES

Source: Wisconsin Department of Natural Resources 608-266-2621
Mirror Lake – Dunn County, Wisconsin DNR Lake Map
Date – May 1970 - Historical Lake Map - Not for Navigation
A Public Document - Please Identify the Source when using it.