


B.M. "X" Spike in large Oak tree on West side of public access  
 Assumed Elev. 100.00'  
 Water Elev. 95.00'

EQUIPMENT RECORDING SONAR MAPPED AUGUST 1966  
 MO. YR.

- TOPOGRAPHIC SYMBOLS
- (B) Brush
  - (PW) Partially wooded
  - (W) Wooded
  - (C) Cleared
  - (P) Pastured
  - (A) Agricultural
  - B.M. Bench Mark
  - Dwelling
  - Resort
  - ||||| Steep slope
  - - - Indefinite shoreline
  - Marsh
  - Spring
  - Intermittent stream
  - Permanent inlet
  - Permanent outlet
  - Dam

- WATER ELEV. 95.00'
- LAKE BOTTOM SYMBOLS
- P. Peat
  - Mk. Muck
  - C. Clay
  - M. Marl
  - Sd. Sand
  - St. Silt
  - Gr. Gravel
  - R. Rubble
  - Br. Bedrock
  - T Submergent vegetation
  - ↓ Emergent vegetation
  - ≡ Floating vegetation
  - Stumps & Snags



◇ Access      ◀ Access with Parking      ◆ Boat Livery  
 Field work by C. Busch, G. Winter, L. Sather Drawn by E. Eaton

SPECIES OF FISH	Abundance		
	Abundant	Common	Rare
Muskie			
N. Pike		X	
Walleye		X	
L. M. Bass			X
S. M. Bass			
Panfish	X		
Trout			

AREA 192.6 ACRES  
 UNDER 3FT. 7%  
 OVER 20FT. 52%  
 VOLUME 3,532.5 ACRE FT.  
 TOTAL ALK. 46 P.P.M.  
 SHORELINE 3.6 MILES  
 MAX. DEPTH 39 FEET

Source: Wisconsin Department of Natural Resources 608-266-2621  
Dunn Lake - Washburn County, Wisconsin DNR Lake Map  
Date – Aug 1966 - Historical Lake Map - Not for Navigation  
A Public Document - Please Identify the Source when using it.