

Instructions: Bold fields must be completed.

Station Summary			
Waterbody Name GOOSE CREEK		Waterbody ID Code 1193400	Sample ID (YYYYMMDD-CY-FD) 20161020-53-02
Sampling Location			Database Key 135787068
SWIMS Station ID 10022750		SWIMS Station Name GOOSE CR. STATION 1 BRIDGE ON RIVER RD	
Latitude 43.52951	Longitude -90.655754	Lat/Long Determination Method (circle) SWIMS SWDV GPS	Datum Used if using GPS WGS84 or NAD83
Basin (WMU) LOWER WISCONSIN		Watershed Name MIDDLE KICKAPOO RIVER	County RICHLAND

Sample and Site Descriptors	
Sample Collector (Last Name, First) JOHN DELANEY	Project Name KICKAPOO AND LITTLE WILLOW RIVER MACROINVERTEB

Sampling Device

Kick Net
 Surber Sampler
 Eckman
 Ponar
 Artificial Substrate
 Hess Sampler
 Other: _____

Habitat Sampled

Riffle
 Run
 Pool
 Other
 Shoreline Composite
 Proportionally-Sampled Habitat
 Littoral Zone
 Profundal Zone
 Wetland

Total Sampling Time (min) 6.0	Estimated Area Sampled (m ²) 3.0	Number of Samples in Composite 1	Replicate No. _____ of _____
----------------------------------	---	-------------------------------------	------------------------------

Reason For Sampling

Least Impacted Reference
 Baseline
 Impact / Treatment Site
 Control Site
 Trend
 Other: _____

Water Temp. (C) 10.3	D.O. (mg/l) 12.12	D.O. (% sat.) 108	pH (su) 8.02	Conductivity (umhos/cm)	Transparency (cm)
-------------------------	----------------------	----------------------	-----------------	-------------------------	-------------------

Water Color

Clear
 Turbid
 Stained

Estimated Stream Velocity (m/s)

Slow (< 0.15 m/s)
 Moderate (0.15 m/s - 0.5 m/s)
 Fast (> 0.5 m/s)

Measured Velocity circle units m/s or f/s	Average Stream Depth of reach (m)	Average Stream Width of reach (m)
---	-----------------------------------	-----------------------------------

Composition of Substrate Sampled (Percent):

Bedrock: _____ Boulders (basketball or larger): 10 Rubble (tennisball to basketball): 30 Gravel (ladybug to tennisball): 40
 Sand: 10 Clay: 10 Silt/Muck: _____ Overhanging Vegetation: _____
 Aquatic Macrophytes: _____ Leaf Snags: _____ Coarse Woody Debris: _____ Other (____): _____

Embeddedness of Substrate at Sample Site (%) 20 Canopy Cover at Sample Site (%) 0

