

Mike Krieg
1731 Tanglewood Trail

Long Lake, Centuria


952-846-8472

↑ North


shady site
slope = 36%

rock pit

1 square = 1 foot
top view



Completed by:
Katelin Holm
8/28/13



Quantities
4-6" rock = 3.5 ft³
filter fabric = 45 ft²