

Instructions: Bold fields must be completed.

Station Summary			
Waterbody Name UNNAMED		Waterbody ID Code 139100	Sample ID (YYYYMMDD-CY-FD) 20171108-20-02
Sampling Location US County K			Database Key 149253340
SWIMS Station ID 10031383		SWIMS Station Name EAST BRANCH TO DE NEVUE CR. SITE ED4A	
Latitude 43.720783	Longitude -88.39979	Lat/Long Determination Method (circle) SWIMS SWDV GPS	Datum Used if using GPS WGS84 or NAD83
Basin (WMU) UPPER FOX		Watershed Name LAKE WINNEBAGO - EAST	County FOND DU LAC

Sample and Site Descriptors	
Sample Collector (Last Name, First) DAVID BOLHA	Project Name EAST DISTRICT FOLLOW UP MONITORING FOR IMPAIREME

Sampling Device

D-Frame Kick Net
 Surber Sampler
 Eckman
 Ponar
 Artificial Substrate
 Hess Sampler
 Other: _____

Habitat Sampled

Riffle
 Run
 Pool
 Other
 Shoreline Composite
 Proportionally-Sampled Habitat
 Littoral Zone
 Profundal Zone
 Wetland

Total Sampling Time (min) 2	Estimated Area Sampled (m²) 1.5	Number of Samples in Composite 1	Replicate No. _____ of _____
---------------------------------------	--	--	-------------------------------------

Reason For Sampling

Least Impacted Reference
 Baseline
 Impact / Treatment Site
 Control Site
 Trend
 Other: Follow-up monitoring

Water Temp. (°F) 4.2°C 39.6°F	D.O. (mg/l) 10.1	D.O. (% sat.) 76.7	pH (su) 8.1	Conductivity (umhos/cm) 842.1	Transparency (cm) 55
---	----------------------------	------------------------------	-----------------------	---	--------------------------------

Water Color

Clear
 Turbid
 Stained

Estimated Stream Velocity (m/s)

Slow (< 0.15 m/s)
 Moderate (0.15 m/s - 0.5 m/s)
 Fast (> 0.5 m/s)

Measured Velocity circle units m/s or f/s	Average Stream Depth of reach (m) .2	Average Stream Width of reach (m) 5.5
--	--	---

Composition of Substrate Sampled (Percent):

Bedrock: _____ Boulders (basketball or larger): _____ Rubble (tennisball to basketball): 30 Gravel (ladybug to tennisball): 50
 Sand: 20 Clay: _____ Silt/Muck: _____ Overhanging Vegetation: _____
 Aquatic Macrophytes: _____ Leaf Snags: _____ Coarse Woody Debris: _____ Other (_____): _____

Embeddedness of Substrate at Sample Site (%) 20
Canopy Cover at Sample Site (%) 90