

Instructions: **Bold** fields must be completed.

Station Summary		
Waterbody Name NARROWS CREEK	Waterbody ID Code 1276400	Sample ID (YYYYMMDD-CY-FD) 20171003-57-02
Sampling Location		Database Key 150534762

SWIMS Station ID 10014259	SWIMS Station Name NARROWS 5		
Latitude 43.45704	Longitude -90.01533	Lat/Long Determination Method (circle) SWIMS SWDV GPS	
Basin (WMU) LOWER WISCONSIN			Datum Used if using GPS WGS84 or NAD83
Watershed Name NARROWS CREEK AND BARABOO RIVER		County SAUK	

Sample and Site Descriptors	
Sample Collector (Last Name, First) JEAN UNMUTH	Project Name SOUTH DISTRICT FOLLOW UP MONITORING FOR IMPAIRM

Sampling Device

D-Frame Kick Net
 Surber Sampler
 Eckman
 Ponar
 Artificial Substrate
 Hess Sampler
 Other: _____

Habitat Sampled

Riffle
 Run
 Pool
 Other
 Shoreline Composite
 Proportionally-Sampled Habitat
 Littoral Zone
 Profundal Zone
 Wetland

Total Sampling Time (min) 8.0	Estimated Area Sampled (m²) 5.0	Number of Samples in Composite 0	Replicate No. _____ of _____
---	--	--	--

Reason For Sampling

Least Impacted Reference
 Baseline
 Impact / Treatment Site
 Control Site
 Trend
 Other: Followup

Water Temp. (C)	D.O. (mg/l)	D.O. (% sat.)	pH (su)	Conductivity (umhos/cm)	Transparency (cm)
------------------------	--------------------	----------------------	----------------	--------------------------------	--------------------------

Water Color	Estimated Stream Velocity (m/s)
<input type="checkbox"/> Clear <input checked="" type="checkbox"/> Turbid <input type="checkbox"/> Stained	<input type="checkbox"/> Slow (< 0.15 m/s) <input checked="" type="checkbox"/> Moderate (0.15 m/s - 0.5 m/s) <input type="checkbox"/> Fast (> 0.5 m/s)

Measured Velocity circle units m/s or f/s	Average Stream Depth of reach (m) 0.10	Average Stream Width of reach (m) 4.5
--	--	---

Composition of Substrate Sampled (Percent):

Bedrock: _____ Boulders (basketball or larger): _____ Rubble (tennisball to basketball): 10 Gravel (ladybug to tennisball): 50
 Sand: _____ Clay: _____ Silt/Muck: 10 Overhanging Vegetation: 20
 Aquatic Macrophytes: _____ Leaf Snags: _____ Coarse Woody Debris: 10 Other (_____): _____
 Embeddedness of Substrate at Sample Site (%): 80 Canopy Cover at Sample Site (%): 0