

Instructions: **Bold** fields must be completed.

Station Summary			
Waterbody Name UNNAMED		Waterbody ID Code 848000	Sample ID (YYYYMMDD-CY-FD) 20171020-28-01
Sampling Location <i>12 m downstream of Spooner Rd NC-311</i>		Database Key 150694034	
SWIMS Station ID 10048577		SWIMS Station Name UNNAMED TRIB (848000) AT SPOONER RD	
Latitude <i>43.14234</i>	Longitude <i>88.67515</i>	Lat/Long Determination Method (circle) SWIMS SWDV GPS	Datum Used if using GPS WGS84 or NAD83
Basin (WMU) UPPER ROCK		Watershed Name SINISSIPPI LAKE	County JEFFERSON

Sample and Site Descriptors	
Sample Collector (Last Name, First) AMRHEIN, JAMES	Project Name SOUTH DISTRICT NC STREAM STRATIFIED SITES 2017

Sampling Device

D-Frame Kick Net
 Surber Sampler
 Eckman
 Ponar
 Artificial Substrate
 Hess Sampler
 Other: _____

Habitat Sampled

Riffle
 Run
 Pool
 Other
 Shoreline Composite
 Proportionally-Sampled Habitat
 Littoral Zone
 Profundal Zone
 Wetland

Total Sampling Time (min) <i>2</i>	Estimated Area Sampled (m ²) <i>2</i>	Number of Samples in Composite <i>1</i>	Replicate No. _____ of _____
---------------------------------------	--	--	------------------------------

Reason For Sampling

Least Impacted Reference
 Baseline
 Impact / Treatment Site
 Control Site
 Trend
 Other: _____

Water Temp. (C) <i>12.3</i>	D.O. (mg/l) <i>8.35</i>	D.O. (% sat.) <i>77.9</i>	pH (su) <i>7.52</i>	Conductivity (umhos/cm) <i>636</i>	Transparency (cm)
--------------------------------	----------------------------	------------------------------	------------------------	---------------------------------------	-------------------

Water Color <input checked="" type="checkbox"/> Clear <input type="checkbox"/> Turbid <input type="checkbox"/> Stained	Estimated Stream Velocity (m/s) <input type="checkbox"/> Slow (< 0.15 m/s) <input checked="" type="checkbox"/> Moderate (0.15 m/s - 0.5 m/s) <input type="checkbox"/> Fast (> 0.5 m/s)
---	---

Measured Velocity circle units m/s or f/s	Average Stream Depth of reach (m)	Average Stream Width of reach (m)
---	-----------------------------------	-----------------------------------

Composition of Substrate Sampled (Percent):

Bedrock: _____ Boulders (basketball or larger): _____ Rubble (tennisball to basketball): *10* Gravel (ladybug to tennisball): *70*
 Sand: *20* Clay: _____ Silt/Muck: _____ Overhanging Vegetation: _____
 Aquatic Macrophytes: _____ Leaf Snags: _____ Coarse Woody Debris: _____ Other (____): _____
 Embeddedness of Substrate at Sample Site (%) *50* Canopy Cover at Sample Site (%) *50*

Stream and Watershed Descriptors

N = Not a problem
 U = Uncertain

PL = Present, Low Impact
 PH = Present, High Impact

Factors that may be influencing Water Resource Integrity		Local	Water-shed	Factors that may be influencing Water Resource Integrity		Local	Water-shed
Biological				Chemical			
Algae: - Diatoms / Periphyton				Chlorine			
- Filamentous Algae				Dissolved Oxygen			
- Planktonic Algae				Nutrients (P, N...)			
Iron Bacteria				Toxics: - Inorganic (Metals)			
Macrophytes				- Organic (PCBs, pesticides...)			
Slimes				Other - Specify:			
Other - Specify:				Sources of Stream Impacts			
				Bank Erosion			
				Point Source - Specify:			
				Pasturing of Livestock			
Bank Erosion				Runoff: - Barnyard			
Channelization: - Upstream				- Construction			
- Downstream				- Cropland			
Hydraulic Scour / Channel Incision				- Urban			
Impoundment: - Upstream				Septic Systems			
- Downstream				Tile Drainage - Organic Soils			
Low Flow				- Mineral Soils			
Sedimentation				Springs			
Sludge				Tributary(s)			
Thermal				Wetland			
Turbidity				Other - Specify:			
Other - Specify:							

Comments

Special Instructions for Laboratory

For Lab Use Only

Sample Sorter	Kate Wilcox	Taxonomist	Dimick Jeffrey	Estimated Percent of Sample Sorted	40%
Date Processed	8/11/14	Specimens Saved	Subsample archived in ABC under 10 Nov 2021		

B2=25 B3=23 C3=31 12/1