

Instructions: Bold fields must be completed.

Station Summary			
Waterbody Name MECAN RIVER		Waterbody ID Code 155000	Sample ID (YYYYMMDD-CY-FD) 20171017-70-02
Sampling Location DS 9th Ave		Database Key 149844414	
SWIMS Station ID 10033877		SWIMS Station Name MECAN RIVER - 9TH AVE (DOWNSTREAM)	
Latitude N44.04518	Longitude W89.44627	Lat/Long Determination Method (circle) SWIMS SWDV GPS	Datum Used if using GPS WGS84 or NAD83
Basin (WMU) UPPER FOX		Watershed Name MECAN RIVER	County WAUSHARA

Sample and Site Descriptors	
Sample Collector (Last Name, First) DAVID BOLHA	Project Name MACROINVERTEBRATE SPATIAL ANALYSIS

Sampling Device

D-Frame Kick Net Surber Sampler Eckman
 Ponar Artificial Substrate Hess Sampler Other: _____

Habitat Sampled

Riffle Run Pool
 Other Shoreline Composite Proportionally-Sampled Habitat
 Littoral Zone Profundal Zone Wetland

Total Sampling Time (min) 1.0	Estimated Area Sampled (m ²) 0.5	Number of Samples in Composite 1	Replicate No. <u>1</u> of <u>2</u>
----------------------------------	---	-------------------------------------	------------------------------------

Reason For Sampling

Least Impacted Reference Baseline Impact / Treatment Site
 Control Site Trend Other: _____

Water Temp. (°F) 9.5 49.1 F	D.O. (mg/l) 9.08	D.O. (% sat.) 79.1	pH (su) 7.75	Conductivity (umhos/cm) 372.5	Transparency (cm) 120
--------------------------------	---------------------	-----------------------	-----------------	----------------------------------	--------------------------

Water Color <input checked="" type="checkbox"/> Clear <input type="checkbox"/> Turbid <input type="checkbox"/> Stained	Estimated Stream Velocity (m/s) <input type="checkbox"/> Slow (< 0.15 m/s) <input checked="" type="checkbox"/> Moderate (0.15 m/s - 0.5 m/s) <input type="checkbox"/> Fast (> 0.5 m/s)
---	---

Measured Velocity 1.56	circle units m/s or f/s	Average Stream Depth of reach (m) 0.3	Average Stream Width of reach (m) 7
---------------------------	----------------------------	--	--

Composition of Substrate Sampled (Percent):

Bedrock: _____ Boulders (basketball or larger): _____ Rubble (tennisball to basketball): 10 Gravel (ladybug to tennisball): 65
 Sand: 25 Clay: _____ Silt/Muck: _____ Overhanging Vegetation: _____
 Aquatic Macrophytes: _____ Leaf Snags: _____ Coarse Woody Debris: _____ Other (____): _____

Embeddedness of Substrate at Sample Site (%) ~~20~~ 20 Canopy Cover at Sample Site (%) 75

#1 30m DS culvert

Stream and Watershed Descriptors

N = Not a problem
 U = Uncertain
 PL = Present, Low Impact
 PH = Present, High Impact

Factors that may be influencing Water Resource Integrity		Local	Water-shed	Factors that may be influencing Water Resource Integrity		Local	Water-shed
Biological				Chemical			
Algae: - Diatoms / Periphyton				Chlorine			
- Filamentous Algae				Dissolved Oxygen			
- Planktonic Algae				Nutrients (P, N...)			
Iron Bacteria				Toxics: - Inorganic (Metals)			
Macrophytes				- Organic (PCBs, pesticides...)			
Slimes				Other - Specify:			
Other - Specify:				Sources of Stream Impacts			
				Bank Erosion			
				Point Source - Specify:			
				Pasturing of Livestock			
Bank Erosion				Runoff: - Barnyard			
Channelization: - Upstream				- Construction			
- Downstream				- Cropland			
Hydraulic Scour / Channel Incision				- Urban			
Impoundment: - Upstream				Septic Systems			
- Downstream				Tile Drainage - Organic Soils			
Low Flow				- Mineral Soils			
Sedimentation				Springs			
Sludge				Tributary(s)			
Thermal				Wetland			
Turbidity				Other - Specify:			
Other - Specify:							

Comments

Special Instructions for Laboratory

For Lab Use Only

Sample Sorter <i>Kiersten Starneck</i>	Taxonomist <i>Dimick, Jeffrey</i>	Estimated Percent of Sample Sorted <i>7%</i>
Date Processed <i>11/13/2018</i>	Specimens Saved <i>Subsample archived in ABL until Feb 2022</i>	

€2=130