

Instructions: Bold fields must be completed.

Station Summary

Waterbody Name PINE RIVER		Waterbody ID Code 247800	Sample ID (YYYYMMDD-CY-FD) 20181012-70-05
Sampling Location			Database Key 168915335
SWIMS Station ID 703071	SWIMS Station Name UPPER PINE RIVER AT CTH AA		
Latitude 44.180267	Longitude -89.252146	Lat/Long Determination Method (circle) SWIMS SWDV <u>GPS</u>	Datum Used if using GPS <u>WGS84</u> or NAD83
Basin (WMU) WOLF RIVER		Watershed Name PINE AND WILLOW RIVERS	County WAUSHARA

Sample and Site Descriptors

Sample Collector (Last Name, First) DAVID BOLHA	Project Name PINE RIVER 319 PROJECT-FUNDED TWA 2018
---	---

Sampling Device

D-Frame Kick Net
 Surber Sampler
 Eckman
 Ponar
 Artificial Substrate
 Hess Sampler
 Other: _____

Habitat Sampled

Riffle
 Run
 Pool
 Other
 Shoreline Composite
 Proportionally-Sampled Habitat
 Littoral Zone
 Profundal Zone
 Wetland

Total Sampling Time (min) 4	Estimated Area Sampled (m²) 2	Number of Samples in Composite 1	Replicate No. <u>1</u> of <u>2</u>
---------------------------------------	--	--	--

Reason For Sampling

Least Impacted Reference
 Baseline
 Impact / Treatment Site
 Control Site
 Trend
 Other: Targeted Watershed Assessment

Water Temp. (C) 8.0	D.O. (mg/l) 10.7	D.O. (% sat.) 92.5	pH (su) 7.9	Conductivity (umhos/cm) 380.8	Transparency (cm) 120
-------------------------------	----------------------------	------------------------------	-----------------------	---	---------------------------------

Water Color <input checked="" type="checkbox"/> Clear <input type="checkbox"/> Turbid <input type="checkbox"/> Stained	Estimated Stream Velocity (m/s) <input type="checkbox"/> Slow (< 0.15 m/s) <input checked="" type="checkbox"/> Moderate (0.15 m/s - 0.5 m/s) <input type="checkbox"/> Fast (> 0.5 m/s)
--	--

Measured Velocity 1.22 (ft/s) → 1.22 (m/s) <small>circle units m/s or f/s</small>	Average Stream Depth of reach (m) 0.32 (inst) 0.35 (avg)	Average Stream Width of reach (m) 3.5
---	--	---

Composition of Substrate Sampled (Percent):

Bedrock: _____ Boulders (basketball or larger): _____ Rubble (tennisball to basketball): 20 Gravel (ladybug to tennisball): 70
 Sand: 10 Clay: _____ Silt/Muck: _____ Overhanging Vegetation: _____
 Aquatic Macrophytes: _____ Leaf Snags: _____ Coarse Woody Debris: _____ Other (_____): _____

Embeddedness of Substrate at Sample Site (%) 30
Canopy Cover at Sample Site (%) 0

Regular + Duplicate

Stream and Watershed Descriptors

N = Not a problem
 U = Uncertain
 PL = Present, Low Impact
 PH = Present, High Impact

Factors that may be influencing Water Resource Integrity	Local	Water-shed	Factors that may be influencing Water Resource Integrity	Local	Water-shed
Biological			Chemical		
Algae: - Diatoms / Periphyton	N	N	Chlorine	N	N
- Filamentous Algae	N	N	Dissolved Oxygen	N	N
- Planktonic Algae	N	N	Nutrients (P, N...)	N	N
Iron Bacteria	N	N	Toxics: - Inorganic (Metals)	N	N
Macrophytes	N	N	- Organic (PCBs, pesticides...)	N	N
Slimes	N	N	Other - Specify:		
Other - Specify:			Sources of Stream Impacts		
			Bank Erosion	N	N
			Point Source - Specify:	N	N
Physical			Pasturing of Livestock	N	N
Bank Erosion	N	N	Runoff: - Barnyard	N	N
Channelization: - Upstream	N	N	- Construction	N	N
- Downstream	N	PL	- Cropland	N	PL
Hydraulic Scour / Channel Incision	N	N	- Urban	N	N
Impoundment: - Upstream	N	N	Septic Systems	N	N
- Downstream	PH	PH	Tile Drainage - Organic Soils	N	N
Low Flow	N	N	- Mineral Soils	N	N
Sedimentation	PH	PH	Springs	PL	PL
Sludge	N	N	Tributary(s)	N	PL
Thermal	N	N	Wetland	N	PL
Turbidity	N	N	Other - Specify:		
Other - Specify:					

Comments

Special Instructions for Laboratory

For Lab Use Only		
Sample Sorter Sam Lamarche	Taxonomist Derrick Jeffrey	Estimated Percent of Sample Sorted 70%
Date Processed 3/1/2019	Specimens Saved Subsample archived in ABL until May 2022	

C3

197 total specs