

Instructions: Bold fields must be completed.

Station Summary

Waterbody Name STONY CREEK		Waterbody ID Code 96100	Sample ID (YYYYMMDD-CY-FD) 20180920-15-03
Sampling Location			Database Key 168775494
SWIMS Station ID 10051133		SWIMS Station Name STONY CREEK AT GEIER RD	
Latitude	Longitude	Lat/Long Determination Method (circle) SWIMS SWDV GPS	Datum Used if using GPS WGS84 or NAD83
Basin (WMU) TWIN - DOOR - KEWAUNEE		Watershed Name STONY CREEK	County DOOR

Sample and Site Descriptors

Sample Collector (Last Name, First) MARY GANSBERG	Project Name NE LAKESHORE TMDL SUPPLEMENTAL MONITORING
---	--

Sampling Device

D-Frame Kick Net Surber Sampler Eckman
 Ponar Artificial Substrate Hess Sampler Other: _____

Habitat Sampled

Riffle Run Pool
 Other Shoreline Composite Proportionally-Sampled Habitat
 Littoral Zone Profundal Zone Wetland

Total Sampling Time (min) 8	Estimated Area Sampled (m²) 0.7	Number of Samples in Composite 1	Replicate No. _____ of _____
---------------------------------------	--	--	--

Reason For Sampling

Least Impacted Reference Baseline Impact / Treatment Site
 Control Site Trend Other: TMDL

Water Temp. (C) 16.9	D.O. (mg/l) 6.8	D.O. (% sat.) 70.2	pH (su) 7.8	Conductivity (umhos/cm) 746	Transparency (cm)
--------------------------------	---------------------------	------------------------------	-----------------------	---------------------------------------	--------------------------

Water Color <input type="checkbox"/> Clear <input type="checkbox"/> Turbid <input checked="" type="checkbox"/> Stained	Estimated Stream Velocity (m/s) <input checked="" type="checkbox"/> Slow (< 0.15 m/s) <input type="checkbox"/> Moderate (0.15 m/s - 0.5 m/s) <input type="checkbox"/> Fast (> 0.5 m/s)
--	--

Measured Velocity circle units m/s or f/s	Average Stream Depth of reach (m) 0.3	Average Stream Width of reach (m) 10
--	---	--

Composition of Substrate Sampled (Percent):

Bedrock: _____ Boulders (basketball or larger): _____ Rubble (tennisball to basketball): 60 Gravel (ladybug to tennisball): 30
 Sand: 10 Clay: _____ Silt/Muck: _____ Overhanging Vegetation: _____
 Aquatic Macrophytes: _____ Leaf Snags: _____ Coarse Woody Debris: _____ Other (____): _____

Embeddedness of Substrate at Sample Site (%) 10 **Canopy Cover at Sample Site (%)** 100