

Instructions: Bold fields must be completed.

Station Summary			
Waterbody Name BRANCH RIVER		Waterbody ID Code 71300	Sample ID (YYYYMMDD-CY-FD) 20191007-36-21
Sampling Location			Database Key 209711241
SWIMS Station ID 363299		SWIMS Station Name BRANCH RIVER AT N UNION RD (2)	
Latitude	Longitude	Lat/Long Determination Method (circle) SWIMS SWDV GPS	Datum Used if using GPS WGS84 or NAD83
Basin (WMU) MANITOWOC		Watershed Name BRANCH RIVER	County MANITOWOC

Sample and Site Descriptors	
Sample Collector (Last Name, First) MARY GANSBERG	Project Name NER LONG-TERM TREND WADEABLE REFERENCE STREAM

Sampling Device

D-Frame Kick Net
 Surber Sampler
 Eckman
 Ponar
 Artificial Substrate
 Hess Sampler
 Other: _____

Habitat Sampled

Riffle
 Run
 Pool
 Other
 Shoreline Composite
 Proportionally-Sampled Habitat
 Littoral Zone
 Profundal Zone
 Wetland

Total Sampling Time (min) 1	Estimated Area Sampled (m ²) 0.2	Number of Samples in Composite 1	Replicate No. _____ of _____
--------------------------------	---	-------------------------------------	------------------------------

Reason For Sampling

Least Impacted Reference
 Baseline
 Impact / Treatment Site
 Control Site
 Trend
 Other: _____

Water Temp. (C) 12.9	D.O. (mg/l) 9.8	D.O. (% sat.) 92.6	pH (su) 8.0	Conductivity (umhos/cm) 574	Transparency (cm) -
-------------------------	--------------------	-----------------------	----------------	--------------------------------	------------------------

Water Color <input type="checkbox"/> Clear <input type="checkbox"/> Turbid <input checked="" type="checkbox"/> Stained	Estimated Stream Velocity (m/s) <input type="checkbox"/> Slow (< 0.15 m/s) <input type="checkbox"/> Moderate (0.15 m/s - 0.5 m/s) <input checked="" type="checkbox"/> Fast (> 0.5 m/s)
---	---

Measured Velocity circle units m/s or f/s	Average Stream Depth of reach (m) 1.0	Average Stream Width of reach (m) 17
---	--	---

Composition of Substrate Sampled (Percent):

Bedrock: _____ Boulders (basketball or larger): _____ Rubble (tennisball to basketball): 70 Gravel (ladybug to tennisball): 20
 Sand: 10 Clay: _____ Silt/Muck: _____ Overhanging Vegetation: _____
 Aquatic Macrophytes: _____ Leaf Snags: _____ Coarse Woody Debris: _____ Other (_____): _____

Embeddedness of Substrate at Sample Site (%) 0
 Canopy Cover at Sample Site (%) 10