

SIC-01

State of Wisconsin  
Department of Natural Resources  
PO Box 7291, Madison WI 53707-7291  
dnr.wi.gov

**Wadeable Macroinvertebrate  
Field Data Report**  
Form 3200-081 (R 8/14) Page 1 of 2

20201014-60-24

Instructions: **Bold** fields must be completed.

**Station Summary**

<b>Waterbody Name</b> SILVER CREEK	<b>Waterbody ID Code</b> 29900	<b>Sample ID (YYYYMMDD-CY-FD)</b> <del>202010141002-SIC-01</del>
---------------------------------------	-----------------------------------	---

<b>Sampling Location</b> US Camp Awanda Road	<b>Database Key</b> 251163141
---	----------------------------------

<b>SWIMS Station ID</b> 603299	<b>SWIMS Station Name</b> SILVER CREEK AT STH 144 WAYSIDE BI
-----------------------------------	---

<b>Latitude</b> 43.5566	<b>Longitude</b> -88.0368	<b>Lat/Long Determination Method (circle)</b> SWIMS SWDV GPS	<b>Datum Used if using GPS</b> WGS84 or NAD83
----------------------------	------------------------------	---	--

<b>Basin (WMU)</b> MILWAUKEE RIVER	<b>Watershed Name</b> NORTH BRANCH MILWAUKEE RIVER	<b>County</b> SHEBOYGAN
---------------------------------------	---	----------------------------

**Sample and Site Descriptors**

<b>Sample Collector (Last Name, First)</b> Watkinson, Arthur	<b>Project Name</b> MILWAUKEE RIVER BASIN AQUATIC MACROINVERTEBRATE
---	--

**Sampling Device**

D-Frame Kick Net     
  Surber Sampler     
  Eckman  
 Ponar     
  Artificial Substrate     
  Hess Sampler     
  Other: \_\_\_\_\_

**Habitat Sampled**

Riffle     
  Run     
  Pool  
 Other     
  Shoreline Composite     
  Proportionally-Sampled Habitat  
 Littoral Zone     
  Profundal Zone     
  Wetland

<b>Total Sampling Time (min)</b> 6	<b>Estimated Area Sampled (m<sup>2</sup>)</b> 1	<b>Number of Samples in Composite</b>	<b>Replicate No.</b> _____ <b>of</b> _____
---------------------------------------	--	---------------------------------------	--

**Reason For Sampling**

Least Impacted Reference     
  Baseline     
  Impact / Treatment Site  
 Control Site     
  Trend     
  Other: Milw. River Supply

<b>Water Temp. (C)</b> 10.46	<b>D.O. (mg/l)</b> 11.04	<b>D.O. (% sat.)</b> 99.1	<b>pH (su)</b> 7.32	<b>Conductivity (umhos/cm)</b> 1009	<b>Transparency (cm)</b> ~75
---------------------------------	-----------------------------	------------------------------	------------------------	--	---------------------------------

<b>Water Color</b> <input type="checkbox"/> Clear <input type="checkbox"/> Turbid <input checked="" type="checkbox"/> Stained	<b>Estimated Stream Velocity (m/s)</b> <input type="checkbox"/> Slow (< 0.15 m/s) <input checked="" type="checkbox"/> Moderate (0.15 m/s - 0.5 m/s) <input type="checkbox"/> Fast (> 0.5 m/s)
--	--

<b>Measured Velocity</b> circle units m/s or f/s	<b>Average Stream Depth of reach (m)</b> .6	<b>Average Stream Width of reach (m)</b> 4
--	--	---

**Composition of Substrate Sampled (Percent):**

Bedrock: \_\_\_\_\_ Boulders (basketball or larger): 5 Rubble (tennisball to basketball): 15 Gravel (ladybug to tennisball): 60  
 Sand: 20 Clay: \_\_\_\_\_ Silt/Muck: \_\_\_\_\_ Overhanging Vegetation: \_\_\_\_\_  
 Aquatic Macrophytes: \_\_\_\_\_ Leaf Snags: \_\_\_\_\_ Coarse Woody Debris: \_\_\_\_\_ Other ( ): \_\_\_\_\_

**Embeddedness of Substrate at Sample Site (%)** 20     
 **Canopy Cover at Sample Site (%)** 40

TDS 647.6