

Chlorophyll a Assessment Summary Report

Name of Lake: Circle Lily Lake

WBIC: 2326700

County: Iron,Vilas

Natural Community: Deep Headwater

Watershed: Manitowish River

REC Impairment Threshold: 14 ug/l

FAL Impairment Threshold: 27 ug/l

NOTE: Values exceeding the REC threshold but not FAL are highlighted in blue; values exceeding the FAL threshold are highlighted in green.

*REC and FAL Exceedances / Years only consider the 2006 to 2010 period. * indicates one or more samples taken, but year does not qualify.*

	REC Exceedances /		FAL Exceedances /		Yearly Averages (ug/l)									
	Years		Years		2010	2009	2008	2007	2006	2005	2004	2003	2002	2001
Whole-Lake Average	0 / 4	Flagged: No	0 / 4	Flagged: No	3.9	4.0	6.8	5.5						
Station #643459, Circle Lily Lake - Deep Hole	0 / 4	Flagged: No	0 / 4	Flagged: No	3.9	4.0	6.8	5.5						
